HISTORIC AMERICAN ENGINEERING RECORD

HAER MINN 27-MINAP 20-

INDEX TO PHOTOGRAPHS

WASHBURN CROSBY MILLING COMPLEX 701-709 South 1st & 2nd Street Minneapolis Hennepin County Minnesota HAER NO. MN-83

Jet Lowe, Photographer, November 1993

GENERAL VIEW:

MN-83-1	NORTHEAST FACADE LOOKING SOUTHWEST AT NO. 1 ELEVATOR, FEED ELEVATOR, "A" MILL AND OFFICE, AND UTILITY BUILDING.
MN-83-2	WEST FACADE LOOKING EAST ELEVATOR NO. 1, FEED ELEVATOR, "A" MILL & OFFICE, AND UTILITY BUILDING.
MN-83-3	NORTH FACADE LOOKING SOUTH AT THE UTILITY BUILDING, "A" MILL & OFFICE, FEED ELEVATOR, AND NO. 1 ELEVATOR.
MN-83-4	NORTH FACADE LOOKING SOUTH AT UTILITY BUILDING, "A" MILL & OFFICE, AND FEED ELEVATOR.
MN-83-5	EAST FACADE LOOKING WEST AT THE NO. 1 ELEVATOR.
MN-83-6	SOUTHEAST FACADE LOOKING NORTHWEST AT NO. 1 ELEVATOR & LOADING SHED, STORAGE SHED, AND HUMBOLDT MILL.
MN-83-7	SOUTH FACADE LOOKING NORTH AT HUMBOLT MILL, STORAGE SHED, AND LOADING SHED OF NO. 1 ELEVATOR.
MN-83-8	SOUTHWEST FACADE LOOKING NORTHEAST AT THE UTILITY BUILDINGS, "A" MILL, AND WHEAT HOUSE.
MN-83-9	WEST FACADE LOOKING EAST AT UTILITY BUILDING AT THE UTILITY BUILDINGS.
MN-83-10	INTERIOR VIEW OF WEST FACADE LOOKING WEST AT FIRE DAMAGE.